

#### The Campaign for Trinity: Making Trinity Stronger and more Welcoming for All!

**Before and After Photos** 

Sexton's House Exterior Repairs












Exterior After Repairs and painting



# Sexton's House interior repairs and renovations

- Redesigned layout
- Created 3<sup>rd</sup> BR
- Painting, carpet, repairs to walls and woodwork



Example of rough condition of interior



Finished results inside









Fix cause of leaks in school building




#### Damage to stone façade from leaks








## Replace rusted A/C units



Coping to eliminate water saturation into walls

Bay in PH was separating from wall and leaking



#### Walkways before and after









Wheelchair walkway under construction







Room for wheelchair in pews

#### Before renovaton


















#### Rusted hinges replaced



### Delivering new air conditioner chillers

Chillers lifted over church






## \$20,000 controller for air conditioning

New fire alarm and sprinkler system \$140,000









## Sprinkler Head in Basement

ED





Doors & walls modified for fire safe stairwell

Stairwell enclosed for fire safety



## **Upcoming Projects**

# Church Lighting Project: Eliminate Dark Pews in Church




# 15 switches control lights in church– convert to digital controls





Restroom Replacement (add accessible)



### Create Storage Room






#### Renovate Serving Area

#### Location for wheelchair lift





#### Parish Hall doors to be refinished and hinges replaced

